

SAAB

SAAB DRIVE, P.O. BOX 697
ORANGE, CONN. 06477
203 795-5671

PARTS

October 30, 1978
DL-358-78

ATTENTION: PARTS MANAGER

To: ALL SAAB DEALERS

Subject: 2.0 LITER CAMSHAFTS

The correct camshafts and cam bearing assemblies for SAAB 99 2.0 liter engines are given below.

<u>CAM</u>	<u>BEARING</u>	<u>APPLICATION</u>
83-52-254 (OEM) 83-58-186 (ALT.)	83-53-518* 83-56-719	1973-74, All with EFI, or Carb
83-56-057	83-56-719	1975 and up with CIS (except Turbo)
83-66-361	83-56-719	1978 and up CIS/Turbo

* Please note that as from 8/78, P/N 83-53-518 is Superseded to P/N 83-56-719 plus cam 83-58-186. If only the cam is needed, P/N 83-52-254 will still be available for some time for 73-74 99's. Cam 83-58-186 has the same lobe profile, but the ramps are longer, giving quieter valve operation. Bearing 83-56-719 must be used with 83-58-186. Approval of this alternate cam for 73-74 99's has been granted by EPA.

National Service and Parts Department

JS/drl